## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,889,284 B1 DATED : May 3, 2005

INVENTOR(S) : Nizar et al.

89,284 B1 Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4,

 $\overline{\text{Line 67, delete "1"}}$  and insert -- =1 --.

Column 6.

Line 18, after "row.", insert -- MA[7.0]=Byte Masks for DQA bus. --.

Column 8,

Line 42, after "generated", insert -- by --.

Column 10,

Line 43, delete "representative" and insert -- responsive --.

Signed and Sealed this

Sixteenth Day of August, 2005

JON W. DUDAS

Director of the United States Patent and Trademark Office